

DATE: 02 IULY 2015

Head Office

8th Floor Old Mutual Centre 3rd Street / Jason Moyo Avenue P.O. Box CY 617 Causeway, Harare Tel; 04 797610-3 / 04 797603-5 Email: pr@zinwa.co.zw info@zinwa.co.zw

BOREHOLE WATER QUALITY ANALYSIS RESULTS

Bacteriological analyses were carried out on contaminated borehole water samples at Cranborne Stores in Harare. The water was passed through a regulator sediment filter and a UV filter system produced by Dr Loyd Muzangwa. The analytical results are as follows

Analytical Tests in Compliance with SAZ 569: 1997

PARAMETER	PRE TREATMENT	POST TREATMENT	Zimbabwe Standards SAZS 560:1997	
			Recommended Limit	Maximum Allowable Limit
Temperature deg C	22.5	22.6	*	*
DO % Saturation	4.2	3.1	*	*
Total Coliforms, cfu/100ml	17 × 10 ³	N.D	0	0
E.coli, cfu/100ml	3 × 10 ³	N.D	0	0
pH units	7.44	7.42	6.5-8.5	6.0-9.0

The results of show that the system effectively removes all the Coliform and E.coli bacteria in the water. The water samples were tested using membrane lauryl sulphate broth filtration method.

However, if you have any challenges, please feel free to contact Mr Nherera on 0779 994 144 (e-mail tnherera@zinwa.co.zw)

Sampled by

R. Marangarire (Q. A Technician)

Analysed by

M. Tinago

(Q.A. Scientist)

Approved by

T. Nherera

(Q.A Scientist)

Date

02 July 2015

Signature:

T. Nherera (Quality Assurance Manager)

Sanyati Catchment P.O Box 554 Gweru Tel: 054 222511 - 4 Fax: 054 220168

Mazoe Catchment P.O Box CY 715 Causeway Harare Tel: 738781 / 3 Fax: 738856

761471

Runde Catchment P.O Box 250 Masvingo Tel: 039 263690 /262950-2 Fax: 039 263972

Save Catchment P.O Box 210 Mutare Tel: 020 60926 Fax: 020 62848

Gwayi Catchment P.O Box 566 Bulawayo Tel: 09 69361-3/67628 Fax: 09 77109

P.O Box 2008 Bulawayo Tel: 09 885191/2/6/8 Fax: 09 882865

P.D. Box CY 817, Causeway, Harans

Combabwe National Water Authority DATA AND PESEARCH SINIT

> Mzingwane Catchment Manyame Catchment P.O Box CY 715 Harare Tel: 702124/793738/32 Fax: 738785